

**SUPLEMENTO A LA AIP DE LA REPÚBLICA ARGENTINA**

Dirección AFS:  
SABBYNYX  
Tel (54 11) 5941 3011  
dianac@anac.gov.ar

**DIRECCIÓN NACIONAL DE INSPECCIÓN DE NAVEGACIÓN AÉREA  
DIRECCIÓN REGULACIÓN NORMAS Y PROCEDIMIENTOS  
DEPARTAMENTO INFORMACIÓN AERONÁUTICA**

BALCARCE 290  
(C1064AAF) – C.A.B.A.  
REPÚBLICA ARGENTINA

**A 06/2022**  
11 de marzo 2022

**A 06. MODIFICACIONES EN AIP VOL II PARTE AD 1.5****AD 1.5 SITUACIÓN DE CERTIFICACIÓN DE AERÓDROMOS/HELIPUERTOS**

<b>NOMBRE DEL AD/HEL INDICADOR DE LUGAR</b>	<b>FECHA DE CERTIFICACIÓN</b>	<b>VALIDEZ DE LA CERTIFICACIÓN</b>	<b>OBSERVACIONES</b>
Aeropuerto Internacional Mendoza / El Plumerillo SAME	24 - OCT - 2019	Sin fecha de expiración	Certificado por ANAC – RAAC Parte 139
Aeropuerto Internacional San Miguel de Tucumán / Teniente Benjamín Matienzo SANT	03 – MAR - 2022	Sin fecha de expiración	Certificado por ANAC – RAAC Parte 139

Afecta:	AIP VOL II AD 1.5
Duración:	Permanente

ACTUALICE SU DOCUMENTACIÓN

**A 06. CHANGES IN AIP VOL II PART AD 1.5****AD 1.5 CERTIFICATION SITUATION OF AERODROMES/HELIPORTS**

<b>AD/HEL NAME PLACE INDICATOR</b>	<b>DATE OF CERTIFICATION</b>	<b>VALIDITY OF THE CERTIFICATION</b>	<b>REMARKS</b>
<i>Mendoza International Airport / El Plumerillo SAME</i>	<i>24 - OCT - 2019</i>	<i>No expiration date</i>	<i>Certificated by ANAC – RAAC Part 139</i>
<i>San Miguel de Tucumán International Airport / Teniente Benjamín Matienzo SANT</i>	<i>3 - MAR - 2022</i>	<i>No expiration date</i>	<i>Certificated by ANAC – RAAC Part 139</i>

<i>It affects:</i>	<i>AIP VOL II AD 1.5</i>
<i>Validity:</i>	<i>Permanent</i>

UPDATE YOUR DOCUMENTS